Product Safety Recall

GEN 2 DTS & Avator Controls

Models Covered	Serial Range
All helm systems with Gen 2 DTS Controls	N/A
All helm systems with Avator Controls	N/A

Identification Pictures



Defect: GEN 2 or Avator Controls fitted to Boats manufactured prior to June 2025 may malfunction.

Hazard: If a malfunction occurs, a horn will sound and gear changes may become disabled and engine power may be limited. This loss of function could potentially cause a collision or result in the boat becoming stranded.

What to do:

- 1. Consumers with GEN 2 DTS or Avator Controls installed should contact their Mercury dealer to arrange to have the Control rectified.
- 2. Consumers should not use their boat until this rectification has been performed.
- 3. Send us an email us if you are unable to return the product or have sold or gifted it to another person

Contact details:

For more information contact Marine Power International on 03 9791 5822 or email merc.info@mercmarine.com

See www.recalls.govt.nz for other New Zealand consumer product recalls